1/4

Fig. 1A

Fig. 1B

Fig. 1C

Fig. 2A

Fig. 2B

Fig. 2C

Fig. 3A

Fig. 3B

Fig. 4

Step 1: Connect bendet plate or profile to bottom plate

**Step 2:** Connect corrugated sheet to bottom plate

**Step 3:** Connect top plate to bendet plate or profile and to corrugated sheet

Fig. 5

Connection panel to panel

Transverse frame

Conection panel to hull

Transverse frame

Fig. 6